





Uni L Rectangular table

Assembly instructions


- 1
- Assemble beams with legs and middle support.
NOTE! Different positions for T-foot and circular base on the beams



Circular base:
Positioned towards the center of the table



T-foot:
Positioned towards the gables of the table





10x/beam
MC6S M6x14





H5




- 2
- Turn the frame around and assemble the brackets



- 3
- Assemble table tops on frame.
NOTE! Skip this part and move to step 4 if you have table with electric




4x/Console
UKT 5x20



TX25



8x/beam
MC6S M6x14



H5





Uni L Rectangular table




Assembly instructions



NOTE! Following steps are for tables with electric.

4

Assemble the cable trays on the beams.
Finish this step by mounting the Power units in the holders.




5

Connect the electrical parts.

NOTE! The electrical cord passes through the leg

NOTE! The electric cord between Power units goes inside the beam.



A = Power unit, 2x data + 1x USB/1x data + 2x USB (EU/FR/UK)

B = Electrical connection 3-ways

C = Electric cord 1m or 2m depending on size of the table

D = Electric cord 3m (EU/UK)



E = Electrical connection 4-ways

F = Power unit, 2x data + 1x USB/1x data + 2x USB (EU/FR/UK)

G = Electric cord 1m

The cord (D) passes through the leg.

On the bottom side of the circular base is a track for the cord.




The cord (C) goes inside the beam.



Uni L Rectangular table

Assembly instructions

6 Assemble table tops on frame



- 4x/Console
UKT 5x20
- TX25
- 8x/beam
MC6S M6x14
- H5

7 Assemble conference lids to the table tops

